



- J0602
- 1 BRN / WHT
  - 2 SKY
  - 3 RED / BLK
  - 4 YLW
  - 5 YLW / RED
  - 6 ORG / BLK
  - 7 GRN
  - 8 GRN / BLK
  - 9 GLY / WHT
  - 10 WHT
  - 11 WHT / ORG
  - 12 WHT / ORG
  - 13 BLK / BLU
  - 14 YLG
  - 15 PNK

- J0603
- 1 ORG
  - 2 PNK / WHT
  - 3 BLU
  - 4 WHT / VLT
  - 5 GRY
  - 6 WHT / BRN
  - 7 WHT / RED
  - 8 WHT / GRN
  - 9 WHT / BLU
  - 10 WHT / ORG
  - 11 WHT / BLK
  - 12 BLK / WHT
  - 13 WHT / VLT
  - 14 SKY / BLK

CONNECTING  
 P001 - J301  
 P002 - J0301  
 P003 - J0303  
 J0203 - P0101  
 J0605 - P0204

FOR X-330D, EXCLUDE THE 14.5Vx2 OUTPUT SECOND WINDING OF TRANSFORMER AND THE CIRCUITRY WHICH BELONGS TO IT.

No.2-1 X-330 · X-330D MECHA & POWER SUPPLY SCHEMATIC DIAGRAM I3818544